| Submit 1 Copy To Appropriate District Office | State of New Mexico | Form C-10 |
|---|--|--|
| District I - (575) 393-6161 | Energy, Minerals and Natural Resources | Revised July 18, 201 |
| 1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283 | | WELL API NO. 30-039-20616 |
| 811 S. First St., Artesia, NM 88210 | OIL CONSERVATION DIVISION | 5. Indicate Type of Lease |
| District III - (505) 334-6178 | 1220 South St. Francis Dr. | STATE STEE |
| 1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> – (505) 476-3460 | Santa Fe, NM 87505 | 6. State Oil & Gas Lease No. |
| 1220 S. St. Francis Dr., Santa Fe, NM 87505 | | E-5114-4 |
| | ES AND REPORTS ON WELLS | 7. Lease Name or Unit Agreement Name |
| (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH | | |
| PROPOSALS.) | ATION FOR PERMIT" (FORM C-101) FOR SUCH | SAN JUAN 29-7 UNIT |
| | Gas Well 🛛 Other | 8. Well Number 105 |
| 2. Name of Operator | RMUCD | 9. OGRID Number |
| HILCORP ENERGY COMPAN 3. Address of Operator | | 372171 10. Pool name or Wildcat |
| 382 ROAD 3100, AZTEC NM 8 | 7410 APR 0 3 2019 | Blanco Mesaverde/Basin Dakota |
| 4. Well Location | DISTRICT III | |
| | The state of the s | m the East line |
| | ship 29N Range 07W NMPM | |
| (1) [1] [1] [2] [2] [2] [2] [2] [2] [2] [2] [2] [2 | 11. Elevation (Show whether DR, RKB, RT, GR, | |
| | 6432' GL | |
| | | |
| 12. Check A | ppropriate Box to Indicate Nature of Noti | ce, Report or Other Data |
| NOTICE OF INT | ENTION TO: | UBSEQUENT REPORT OF: |
| PERFORM REMEDIAL WORK | PLUG AND ABANDON REMEDIAL W | |
| TEMPORARILY ABANDON | | DRILLING OPNS. □ P AND A □ |
| PULL OR ALTER CASING | MULTIPLE COMPL CASING/CEM | |
| DOWNHOLE COMMINGLE | MOLTIFLE COMPL CASING/CEN | IENT JOB |
| CLOSED-LOOP SYSTEM | | |
| OTHER: | □ OTHER: ☑ F | RECOMPLETE |
| | eted operations. (Clearly state all pertinent details | |
| | k). SEE RULE 19.15.7.14 NMAC. For Multiple | |
| proposed completion or reco | | |
| The above well was recompleted to the | a Masayarda as follows: | |
| The above well was recompleted to the | e Mesaverde as follows. | |
| | oumper spring. Tag 23' fill on bottom. MIRU. LD | |
| NU BOP & kill spool. PT Pipe & blin | d rams 250# low & 2500# high, test good. Unsea | at & LD tbg hanger, tag 20' fill on bottom. TOH. |
| Scan-X scanned 2-3/8" tbg. PU strap | & rabbit in hole w/ 3-3/4" junk mill & csg scraper | r on 2-3/8" tbg. SDFN. |
| 3/8/2010 _ TIU w/ 2 7/9" innl mill 9- | csg scraper to 6600'. TOH, LD mill & csg scrape | or DII TIH & set 4.5" CIRD @ 6500' I and hal |
| | 6500'- surface to 640# x 10 min, good test. SDF1 | |
| 0015 | South State to one A To min, good test. SDIT | |
| | TOH w/ 2-3/8" tbg & setting tool. RU Basin WL | |
| Wellcheck. PT 4.5" csg 6500' to surfa | ace 2500# x 10 min, good test. TIH w/tbg. TOH, I | LD tbg. RD power tongs & rig floor. ND BOP & |
| | 4.5" csg stub & NU 7-1/16" tbg head. PT tbg head | |
| water. RU Wellcheck. PT 4.5" csg fro | om 6500'-surface to 4000# x 30 min, good test. RI | D Wellcheck. SI well. WO frac. Con't Page 2 |
| Γ | | |
| Spud Date: | Rig Release Date: | |
| | | |
| | | |
| I hereby certify that the information a | bove is true and complete to the best of my knowl | ledge and belief. |
| 10 | and the second of the kilowi | |
| SIGNATURE MORYLENE W | Office TITLE Operations/Regulato | ry Tech-Sr. DATE: 4-2-19 |
| T | Desire II | DUONE SOS SCA OSSO |
| Type or print nameCherylene Wes | ton E-mail address: <u>cweston@hilcorp.com</u> | nPHONE: _505-564-0779 |
| For State Use Only | ///// | |
| APPROVED BY: Del 1 | ER TITLE IT 4858 | Peresisor DATE 4-19-19 |
| Conditions of Approval (if any): | ^/ | |
| | FV | |
| | | |

3/20/2019 MIRU Halliburton & Basin WL. RU frac & N2. RIH & **perf Lower Pt. Lookout** w/0.34" diam, select fire 1 SPF @ 5654', 5658', 5669', 5674', 5683', 5692', 5695', 5703', 5715', 5718', 5735', 5746' = **12 holes**. Test fluid & N2 lines to 5000#, tests good. **Frac Lower Pt.** w/56,870 gals 70Q #20 gel foam @ 40 BPM, 71,385# premium 20/40 sand, total N2: 690,963 SCF. MIRU flowback crew. Open/unload well overnight.

3/21/2019 Test fluid & N2 lines to 5000#, test good. MIRU Basin WL. RIH & **Perf Upper Pt. Lookout** w/ 0.34" diam, select fire 1 SPF @ 5450', 5458', 5465', 5471', 5482', 5487', 5497', 5504', 5512', 5526', 5532', 5539', 5545', 5557', 5564', 5577', 5583', 5602', 5609', 5623' = **20 holes. Frac Upper Pt. Lookout** w/ 55,840 gal 70Q #20 gel foam @ 50 BPM, 72,690# 20/40 white sand, total N2: 521,999 SCF and flushed w/66 bbls. **Set frac plug @ 5430'**. **Perf Menefee** w/ 0.34" diam, select fire 1 SPF @ 5112', 5117', 5150', 5157', 5164', 5178', 5199', 5204', 5221', 5231', 5241', 5305', 5309', 5326', 5334', 5341', 5344', 5370', 5374', 5382', 5388' = **21 holes. Frac Menefee** w/ 95,955 gal 70Q #20 gel foam @ 50 BPM, 154,105# 20/40 white sand, total N2: 1.05 MM SCF, flushed w/ 57 fluid bbls. RU Basin WL. **Set frac plug @ 5104'**. **Perf Cliffhouse** w/ 0.34" diam, select fire 1 SPF @ 4925', 4948', 4995', 5004', 5014', 5021', 5028', 5034', 5053', 5060', 5067', 5080', 5088', 5100' = **14 holes. Frac Cliffhouse** w/ 63,437 gals 70Q #20 gel foam @ 30 BPM, 96,800# 20/40 white sand, total N2: 669,239 SCF, flushed w/ 77 fluid bbls. RU Basin WL, RIH **set kill plug @ 4010'**. RDMO frac & WL.

3/22/2019 MIRU. ND WH, NU BOP. RU Wellcheck. Several attempts to PT BOP pipe & blind rams. Psi loss on high test to 2000#. No visible leaks on BOP. Made 2 runs to plug w/SL. Nothing found. SDFN.

3/23/2019 RU Wellcheck. Pull tbg hanger. PU new double seal tbg hanger & re-set tbg head. PSI up on BOP, found small leak in valve body. Isolate leak. Test BOP 300# low/2100# high, good test. RD Well check. MU 3-7/8" mill. TIH to 1st plug @ 4010'. RU PS. Unload hole w/air. Est 12 bbl/hr air/foam mist @ 1300 CFM & 1.5 gal/hr w/foamer & corrosion inhibitor. **MO CIBP @ 4010'**. CO. PU tbg & TIH to 5039', tag fill. 2nd plug @ 5104'. TOH to 4010'. SDFN.

3/24/2019 TIH from 1040' - 5103'. RU PS w/ air foam mist @ 1300 CFM, MO plug @ 5104'. Circ hole clean. PU more tbg. RIH & tag fill @ 5383'. CO fill w/ air/mist & MO plug @ 5430'. Bucket test: 1-2 cups sand. Pump 3 bbl sweep. Clean up hole. SD air unit. PU & TIH w/ 3-7/8" mill to 6324'. Tag 176' fill on top of CIBP @ 6500'. CO frac sand from 6324'-6449'. Blow well around, pump 3 bbl sweep to clean up hole. Med/heavy sand returns during CO. TOH to 4010'. SWI & SDFN.

3/25/2019 BDW. TIH from 4010' to 6428'. 21' fill overnight. RU PS. Est 12 bbl/hr. air/foam mist. CO from 6428' to CIBP @ 6500' w/med sand returns. Blow on well @ 6500' with air/foam mist. Sand reduced to ½ cup per bucket test. Flow test. Cont CO with air/foam mist until sand down to trace. **MO CIBP @ 6500'**. TIH w/ mill to 7720' & tag up 48' from PBTD @ 7768'. RU PS, est circ w/12 bbl/hr air/foam. CO fill 7720' – 7758'. Circ hole clean to trace of sand. TOOH to 4010'. SDFN.

3/26/2019 BDW. TOH w/ tbg and mill @ 4010'. Kill well w/ 30 bbls water. Drift in hole w/ 2-3/8" prod string. Tag 12' fill @ 7746'. RU swivel, CO fill to 7758'. Clean up well. Returns down to tsp in bucket test. Land 243 jts. 2-3/8" 4.7# J-55 tbg set @ 7690' (SN @ 7688'). RD floor, ND BOP, NU WH. RR @ 1700 hrs.

This well is producing as a MV/DK with an approved Test Allowable C-104 & is waiting on RC C-104 approval.

Well will be a MV/DK commingled well per DHC-4940.