

## NEW MEXICO EMERGY, MOMERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC NM 87410

AZTEC NM 87410 (505) 334-6178 FAX: (505) 334-6170 http://emnrd.state.nm.us/ocd/District III/3distric.htm

## **BRADENHEAD TEST REPORT**

(submit 1 copy to above address)

Date of Test 4/23/19 Operator_ENDURING RESOURCES IV LLC_API #30-039-20158	
Property Name_RINCON UNIT_Well No. 131 Location: Unit K Section 36 Township 27N Range 07W	
Well Status(Shut-In or Producing) Initial PSI: Tubing 2 / Intermediate // Casing 24 Bradenhead	
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH	
PRESSURE  Testing Bradenhead INTERM  BH Int Csg Int Csg	FLOW CHARACTERISTICS BRADENHEAD INTERMEDIATE
TIME S 240	Steady Flow
10 min 0 240	Surges
15 min 241	Down to Nothing
20 min 241	Nothing
25 min 241	Gas
30 min 24(	Gas & Water
	Water
If bradenhead flowed water, check all of the descriptions that apply below:	
CLEAR FRESH SALTY SULFUR BLACK	
5 MINUTE SHUT-IN PRESSURE BRADENHEAD O INTERMEDIATE A	
REMARKS: NA	
	NMOCD
	MAY 0 2 2019
	nessBISTRICT
HSF Tech (Position)	
E-mail address Dockher Co Enduring Resources, com	