



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

MECHANICAL INTEGRITY TEST REPORT

(TA OR UIC)

Date of Test 26-APR-2019 Operator HILCORP API # 30-0 45-28358

Property Name SAN JUAN 32-7 Well # 217 Location: Unit 1 Sec 4 Twn 31 Rge 7

Land Type:

State _____
Federal ☒ _____
Private _____
Indian _____

Well Type:

Water Injection _____
Salt Water Disposal _____
Gas Injection _____
Producing Oil/Gas ☒ _____
Pressure observation _____

Temporarily Abandoned Well (Y/N): _____ TA Expires: _____

Casing Pres. _____ Tbg. SI Pres. _____ Max. Inj. Pres. _____
Bradenhead Pres. _____ Tbg. Inj. Pres. _____
Tubing Pres. _____
Int. Casing Pres. _____

Pressured annulus up to 580 psi. for 30 mins. Test passed/failed

REMARKS: 1000 PSI SPRING 60 MINUTE CHECK

TUB CASING WAS PRESSURED TO 580 PSI AND
PRESSURE HELD FOR THE ENTIRE TEST

By [Signature]
(Operator Representative)

Witness [Signature]
(NMOCD)

(Position)

DISTRICT 111

APR 29 2019

NMOCD

Revised 02-11-02