



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5-1-19 Operator: Enervest Operating, LLC API # 30-039-24162 ✓

Property Name: Hill Trust Fed Com Well No. 01 Location: Unit: F Section: 5 Township: 25N Range: 2W ✓

Well Status (Shut-In or Producing) Initial PSI: Tubing 58 Intermediate N/A Casing 85 Bradenhead 85

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead		INTERM		
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>85</u>		<u>85</u>		
10 min	<u>85</u>		<u>85</u>		
15 min	<u>85</u>		<u>85</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing ✓	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 85

INTERMEDIATE N/A

REMARKS:

No puff dead, Nothing after 5 minute shut in

By Robert Cantu
Operator
(Position)

Witness _____

E-mail address _____

NMOCD

MAY 09 2019

DISTRICT III