



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170

[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

NMOC

MAY 17 2019

DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5-17-19 Operator Hilcorp API #30-0 39-26692
Property Name SS287 Well No. 189F Location: Unit Section 35 Township 28 Range 7
Well Status (Shut-In or Producing) Initial PSI: Tubing 82 Intermediate 0 Casing 83 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	0	80	0	78
10 min	0	0	75	0	78
15 min	0	0	79	0	80
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		✓
Nothing	✓	
Gas		✓
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 0

REMARKS:

Plunger hit at 7 min 40 sec. - Nothing when opened - Nothing w. hen opened after 5 min shut in. Long puff to clear in 3 seconds. Nothing when opened after 5 min shut in.

By [Signature] Witness [Signature]

(Position)

E-mail address

Packer in casing close to well has water gas & oil. No hole in casing