



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 2-MAY-2019 Operator HILLCO API #30-045-24/390

Property Name SAN JUAN 32-7 Well No. 62 Location: Unit M Section 27 Township 32 Range 7

Well Status(Shut-In or Producing) Initial PSI: Tubing NA Intermediate 0 Casing 580 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	0	580	0	580
10 min	0	0	580	0	580
15 min	0	0	580	0	580
20 min	0	0		0	
25 min	0	0		0	
30 min	0	0		0	

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing	X	✓
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD _____ INTERMEDIATE _____

REMARKS: OPENED THE BRADENHEAD AND NOTHING CAME OUT.

OPENED THE INTERMEDIATE AND NOTHING CAME OUT.

By Roma Phillips
Consultant
(Position)

Witness John D. Brown

E-mail address _____

NMOC
MAY 02 2019
DISTRICT III