



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

MECHANICAL INTEGRITY TEST REPORT (TA OR UIC)

Date of Test 2-MAY-2019 Operator HILCORP API # 30-0 45 24390

Property Name SAN JUAN 32-7 Well # 62 Location: Unit 18 Sec 27 Twn 32 Rge 7

Land Type:

State _____
Federal X
Private _____
Indian _____

Well Type:

Water Injection _____
Salt Water Disposal _____
Gas Injection _____
Producing Oil/Gas X
Pressure observation _____

Temporarily Abandoned Well (Y/N): _____ TA Expires: _____

Casing Pres. _____
Cradenhead Pres. _____
Tubing Pres. _____
Int. Casing Pres. _____

Tbg. SI Pres. _____
Tbg. Inj. Pres. _____

Max. Inj. Pres. _____

Pressured annulus up to _____ psi. for _____ mins. Test passed/failed

REMARKS: 1000 PSI SPRING, 40 MINUTE CLOCK
THE CASING WAS PRESSURED UPTO 580 PSI AND
PRESSURE HELD FOR THE ENTIRE TEST.

by _____
(Operator Representative)
Dan Phillips Consultant
(Position)

Witness [Signature]
(NMOCD)

NMOCD

MAY 02 2019

DISTRICT III

Revised 02-11-02