



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 1-June-2019 Operator HILCAP API #30-0 39-07114

Property Name SAN JUAN 27S Well No. 86 Location: Unit M Section 9 Township 27 Range 5

Well Status(Shut-In or Producing) Initial PSI: Tubing 0 Intermediate NA Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	NA	570		
10 min	0		580		
15 min	0		580	NA	
20 min	0		580		
25 min	0		580		
30 min	0		580		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	X
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR 0 FRESH 0 SALTY 0 SULFUR 0 BLACK 0

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE NA

REMARKS: OPENED THE BRADENHEAD AND NOTHING CAME OUT

By Don Shurt
Onsite Supervisor
(Position)

Witness [Signature]

E-mail address _____

NMOC

MAY 31 2019

DISTRICT III