



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

NMOC

MAY 30 2019

DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

OIL CONSERVATION DIVISION

AZTEC DISTRICT OFFICE

1000 RIO BRAZOS ROAD

AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170

[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

Date of Test 5-29-19 Operator Hilcorp Energy Co API #30-0 45-29485
Property Name Allison Wt Well No. 27M Location: Unit Section 30 Township 32 Range 6
Well Status(Shut-In or Producing) Initial PSI: Tubing 99 Intermediate N/A Casing 129 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>117</u>		
10 min	<u>0</u>		<u>119</u>		
15 min	<u>0</u>		<u>121</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	<u> </u>
Nothing	
Gas	<u> </u>
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS:

Started producing when taking initial pressures -
Puff when opened. Nothing when opened after
5 min shut in.

By [Signature]

Witness [Signature]

(Position)

E-mail address