

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

RECEIVED

FORM APPROVED  
OMB No. 1004-0137  
Expires: July 31, 2010

MAY 13 2019

5. Lease Serial No.

NMNM0546

6. If Indian, Allottee or Tribe Name

Farmington Field Office  
Bureau of Land Management

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on page 2.

1. Type of Well

☐ Oil Well

☒ Gas Well

☐ Other

2. Name of Operator

Hilcorp Energy Company

3a. Address

382 Road 3100, Aztec, NM 87410

3b. Phone No. (include area code)

505-599-3400

7. If Unit of CA/Agreement, Name and/or No.

8. Well Name and No.

MADDOX WN FEDERAL 12

9. API Well No.

3004534141

10. Field and Pool or Exploratory Area

BASIN FRUITLAND COAL

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Surface Unit F (SENW), 1437' FNL & 1634' FWL, Sec. 13, T030N, R013W

11. Country or Parish, State

SAN JUAN, New Mexico

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input checked="" type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	Interim Reclamation
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof.

If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 must be filed once Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

Hilcorp Energy Company conducted a legacy interim reclamation inspection on 5/9/2019 with BLM Inspector Bob Switzer and received approval for the reclamation BMPs on the subject well.

NMOCB

MAY 28 2019

DISTRICT III

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)

Kandis Roland

Title Operations/Regulatory Technician - Sr.

Signature

Kandis Roland

Date 5/10/2019

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Accepted for Record

Title

MAY 22 2019  
Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instruction on page 2)

NMOCB

RCC Reclamation Completion				Location Name: MADDOX WN FEDERAL 12		Date: Revision 3 (3/21/17)																	
AP#: 3004534141				UL-Sec-Twn-Rng: F 13 030N 013W		Lat/Long: 36.8164, -108.1595 NAD 27																	
Surface Owner:				Lease#: NMNM0546		County/State: SAN JUAN, NM																	
Pipeline Owner: ENT				Twin/Co-Locate Well Name & Operator:																			
Onsite: Bobby Spearman		Agency Inspector: <i>Bob Spearman</i>		Contractor:		Seed Mix:																	
Interim Reclamation			Completed	Incomplete	N/A	Final Reclamation			Completed	Incomplete	N/A	Remediation			Completed	Incomplete	N/A						
Have pit sample results been approved																							
Has water been removed from pit																							
Have pit marker photos been taken																							
Has certificate of waste been issued & approved																							
Have all pit contents been removed																							
Has sample after content removal been taken																							
Is location contoured																							
Is there 4' of cover over pit																							
Has top soil been spread evenly																							
Has all non-native gravel been buried or removed																							
Has pit liner been removed																							
Has all trash been removed																							
Have all weeds been removed																							
Teardrop allows vehicle access to all facilities																							
Drainage ditches allow adequate run off																							
All non-traffic areas disked properly																							
All non-traffic areas seeded																							
Seeded areas have been mulched																							
Noxious weeds have been removed or sprayed																							
Invasive weeds have been removed or sprayed																							
Barriers set to deter traffic																							
Silt traps are functional																							
Culverts are functional																							
Upper diversion is functional																							
Erosion under control																							
Photo transect installed																							
Have wellhead cages and jersey barriers been removed																							
Have reclamation pictures been taken																							
Growth at least 70%																							
Agency Inspection Date: 5/9/19																							
Sundry is ready to file																							
Comments:								Comments:								Comments:							