

NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District III/3distric.htm

UN 1 2 2019

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

DISTRICT 111

Date of Test 6/12/2019 Operator Logos Operating API #30-045 - 07250		
Property Name Angel Peak & Well No. 25 Location: Unit N Section 24 Township 28 Range 11		
Well Status (Shut-In) or Producing) Initial PSI: Tubing 97 Intermediate NA Casing 96 Bradenhead 0.1		
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH		
PRESSURE Testing Bradenhead INTERM BH Int Csg Int Csg	FLOW CHARACTERISTICS BRADENHEAD INTERMEDIATE	
TIME 5 min 0 96	Steady Flow	
10 min D 97	Surges	
15 min D 97	Down to Nothing	
20 min 0 97	Nothing	
25 min D 97	Gas	
30 min 97	Gas & Water	
	Water	6
If bradenhead flowed water, check all of the descriptions that apply below:		
CLEAR FRESH SALTY SULFUR BLACK		
5 MINUTE SHUT-IN PRESSURE BRADENHEAD INTERMEDIATE NA		
BH through 14" opening, no pressure when opening, nothing following 5 min shatin		
By Eugene Burbank Witness Joneth. Kully Production Former (Position) F-mail address		