



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170

[http://emnr.state.nm.us/ocd/District III/district.htm](http://emnr.state.nm.us/ocd/District%20III/district.htm)

NMOC

JUN 21 2019

DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6-21-19 Operator Hilcorp Energy API #30-0 45-23859
Property Name Hare Gas Com Well No. 1E Location: Unit 6 Section 14 Township 29 Range 11
Well Status (Shut-In or Producing) Initial PSI: Tubing 26 Intermediate Casing 29 Bradenhead 8

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead		INTERM		
	BH	Int	Csg	Int	Csg
TIME					
5 min	0		29		
10 min	0		29		
15 min	0		29		
20 min	0		36		
25 min	0		26		
30 min	0		26		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow <u>- water</u>	
Surges	
Down to Nothing	
Nothing	
Gas	
Gas & Water <u>/</u>	<u>1</u>
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK /

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 6

INTERMEDIATE

REMARKS:

tank gauge start 36.7 - 1st when opened
started flowing black water -
water sample has been taken - 4 gallons.
By John Ham Witness Monica Cuckling

(Position)

E-mail address