



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

MECHANICAL INTEGRITY TEST REPORT (TA OR UIC)

Date of Test 6-10-2019 Operator Hilcorp Energy API # 30-045-24022

Property Name Lawson Well # 2E Location: Unit 0 Sec 31 Twn 32 Rge 11

Land Type:

State _____
Federal X
Private _____
Indian _____

NMOCD
JUN 10 2019
DISTRICT III

Well Type:

Water Injection _____
Salt Water Disposal _____
Gas Injection _____
Producing Oil/Gas X
Pressure observation _____

Temporarily Abandoned Well (X): Workover TA Expires: _____

Casing Pres. 0 Tbg. SI Pres. _____ Max. Inj. Pres. _____
Bradenhead Pres. 0 Tbg. Inj. Pres. _____
Tubing Pres. 0
Int. Casing Pres. _____

Pressured annulus up to 560 psi. for _____ mins. Test passed/failed

REMARKS: Pressured up to 560 psi - 560psi at 5min - 560psi at 10min - 560psi 15min -
slight drop to approx 555psi at 20min - 550 psi at 25min - 550psi at 30min - Had
total loss of 10psi in 30min -

CTBP 7480'

last cal wellcheck unit 5
3-13-19 10000# spring 1/hr clock/check

By [Signature] Witness [Signature]
(Operator Representative) (NMOCD)

(Position)

Revised 02-11-02