



(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District II/3ddistrict.htm](http://emnrd.state.nm.us/ocd/District%20II/3ddistrict.htm)

NMOC D

JUN 11 2019

DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6.11.19 Operator W. Sun Prod. API #30-0 45-25298

Property Name Sanchez O'Brien SWD Well No. 1 Location: Unit Section 6 Township 54 Range 9

Well Status(Shut-In or Producing) Initial PSI: Tubing 750 Intermediate ✓ Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0		0		
10 min	0		0		
15 min	0		0		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE

REMARKS:

REMARKS: Nothing when opened - Nothing when
opened after 5 min shut in

By Loren H. Long

Witness 1 / 1 Onuma J. Williams

(Position)

E-mail address _____