



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 11 JUNE 2019 Operator BP API #30-0 45-26901

Property Name NORTH EAST BANCROFT Well No. 404 Location: Unit E Section 34 Township 31 Range 7

Well Status(Shut-In or Producing) Initial PSI: Tubing Intermediate N/A Casing 550 Bradenhead 20

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	N/A	550		
10 min	0		540		
15 min	0		540	N/A	
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	X	
Nothing		N/A
Gas	X	
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD INTERMEDIATE N/A

REMARKS: OPENED THE BRADENHEAD AND IT BLEW DOWN TO NOTHING IN 34 SECONDS.

By PL [Signature]
WSL
(Position)

Witness [Signature]
NMOCB

E-mail address

JUN 12 2019

DISTRICT III