



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

MECHANICAL INTEGRITY TEST REPORT

(TA OR UIC)

Date of Test 6.12.19 Operator Agua Moss API # 30-0 45-30922
Property Name Petty Lady 30-11-34 Well # 1 Location: Unit J Sec 34 Twn 30 Rge 11

Land Type:

State _____
Federal _____
Private / _____
Indian _____

Well Type:

Water Injection _____
Salt Water Disposal / _____
Gas Injection _____
Producing Oil/Gas _____
Pressure observation _____

NMOC
JUN 12 2019
DISTRICT III

Temporarily Abandoned Well (Y/N) (Y) TA Expires: _____

Casing Pres. 0 Tbg. SI Pres. _____ Max. Inj. Pres. 1350
Bradenhead Pres. 0 Tbg. Inj. Pres. _____
Tubing Pres. _____
Int. Casing Pres. N/A

Pressured annulus up to 465 psi. for 30 mins. Test passed/failed (Y)


REMARKS: MIT prior to step rate test
factor set 3700 dropped to 462 & held
top of 3762

By [Signature]
(Operator Representative)

Witness [Signature]
(NMOC)

Engineer
(Position)

Revised 02-11-02



Graphic Controls

30-045-30922

CHART NO. MC MP-1000-IHR

METER _____

CHART PUT ON

9:58

M

TAKEN OFF

10:32

M

LOCATION

Pretty Lady #1

REMARKS

MIT

NMOCB

JUN 12 2019

DISTRICT III

Monica Treckler
Monica Treckler

Monica Treckler
NMOCB

6.12.19

Passer Prior to sta 21 at least