



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3distric.htm)

NMOCd

JUN 11 2019

DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6-11-19 Operator Insured API #30-0 4532086
Property Name Mesa SW Well No. 4 Location: Unit 16 Section 16 Township 24 Range 8
Well Status (Shut-In or Producing) Initial PSI: Tubing 450 Intermediate N/A Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE					
	BH	Bradenhead Int	Csg	INTERM Int	Csg	
TIME	<u>0</u>		<u>0</u>			
5 min	<u>0</u>		<u>0</u>			
10 min	<u>0</u>		<u>0</u>			
15 min	<u>0</u>		<u>0</u>			
20 min						
25 min						
30 min						

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	<u>/</u>
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS:

light blow to dead at 15 seconds - nothing
when opened after 5 min shut in

By Jason Hestep

Witness Mona Tuckling

(Position)

E-mail address _____