



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District II/3district.htm](http://emnrd.state.nm.us/ocd/District%20II/3district.htm)

NMOC

JUN 21 2019

DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6.21.19 Operator Hilco Energy API #30-0 45-35187
Property Name Hudson Well No. SM Location: Unit 17 Township 31 Range 10
Well Status(Shut-In or Producing) Initial PSI: Tubing 68 Intermediate 0 Casing 98 Bradenhead 4

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
5 min	0	0	96	0	95
10 min	0	0	95	0	95
15 min	0	0	95	0	95
20 min	0	0	95		
25 min	0	0	95		
30 min	0	0	95		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow <u>/ vapors</u>	
Surges	
Down to Nothing	<u>/</u>
Nothing	
Gas <u>/</u>	<u>/</u>
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0 INTERMEDIATE 0

REMARKS:

BH - medium blow to vapors at 31 seconds.
for rest of 30 minute test. Int - puff to head when
opened. Nothing when opened after 5 min shut in.
By Wayne Pearson Witness Monica Gehlman

(Position)

E-mail address _____