



NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
[http://omnr.state.nm.us/ocd/District 113/district.htm](http://omnr.state.nm.us/ocd/District%20113/district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5-20-19 Operator Dominic Reed API # 30-0 31-20301

Property Name Santa Rosa Well No. 47 Location: Unit C Section 12 Township 17 Range 9

Well Status (Shut-In or Producing) Initial PSI: Tubing 0 Intermediate 1/2 Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE					
	Bradenhead	INTERM				
	BH	Int	Csg	Int	Csg	
TIME						
5 min	<u>0</u>		<u>0</u>			
10 min	<u>0</u>		<u>0</u>			
15 min	<u>0</u>		<u>0</u>			
20 min						
25 min						
30 min						

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	<input checked="" type="checkbox"/>
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ☐ FRESH ☐ SALTY ☐ SULFUR ☐ BLACK ☐

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 0

REMARKS: nothing when opened valve on BH

By [Signature]  
(Position)

Witness [Signature]

E-mail address \_\_\_\_\_

NMOC  
JUN 11 2019  
DISTRICT 111