

## NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-8178 FAX: (505) 534-8170
http://emrud.state.um.ls/ocd/District IE/3distric.htm

## **BRADENHEAD TEST REPORT**

(submit 1 copy to above address)

	copy to above address)
Date of Test (0-5-10 Operator)	Dominion Prodapi#30-031-20844
Property Name 5H Well No. 4 Location: Unit Section 17 Township Takange 9 N	
Well Status (Shut-In or Producing) Initial PSI: Tubing O Intermediate Casing D Bradenhead	
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH	
PRESSURE Testing Bradenhead INTERM BH Int Csg Int Csg	FLOW CHARACTERISTICS BRADENHEAD INTERMEDIATE
TIME 5 min 8 0	Steady Flow
10 min 0 0	Surges_
15 min 8 O	Down to Nothing
20 min	Nothing
25 min	Gas
30 min_	Gas & Water
	Water
If bradenhead flowed water, check all of the descriptions that apply below:	
CLEAR FRESH SALTY SULFUR BLACK	
5 MINUTE SHUT-IN PRESSURE BRADENHEAD O INTERMEDIATE	
REMARKS: costhing when spend, nothing efter Sman	
Shut in	
By Witness Witness	
E-mail address	NMOCD
	JUN 1 1 2019

DISTRICT III