

## NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District III/3distric.htm

## **BRADENHEAD TEST REPORT**

(submit 1 copy to above address)

Date of Test 7/4/19 Operator_ENDURING RESOURCES IV LLC_API #30-039-06874	
Property Name_RINCON UNIT_Well No. 038 Location: Unit I Section 26 Township 27N Range 07W	
Well Status(Shut-In or Producing) Initial PSI: Tubing 25 Intermediate N/A Casing 26 Bradenhead	
PRESSURE Testing Bradenhead INTERM BH Int Csg Int Csg TIME 5 min 26  10 min 26  20 min 25 min 30 min 30 min	FLOW CHARACTERISTICS BRADENHEAD INTERMEDIATE  Steady Flow Surges  Down to Nothing  Nothing  Gas  Gas & Water  Water
If bradenhead flowed water, check all of the descriptions that apply below:  CLEAR FRESH SALTY SULFUR BLACK	
5 MINUTE SHUT-IN PRESSURE BRADENHEAD INTERMEDIATE REMARKS:	
By John Dockter Witness  HSE Tech (Position)  E-mail address J Dockter & Endusing Resources. Gran	
	7/10/19