



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3ddistrict.htm](http://emnr.state.nm.us/ocd/District%20III/3ddistrict.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7/2/19 Operator ENDURING RESOURCES IV LLC API #30-039-06985

Property Name RINCON UNIT Well No. 113 Location: Unit H Section 20 Township 27N Range 06W

Well Status (Shut-In or Producing) Producing Initial PSI: Tubing 26 Intermediate N/A Casing 26 Bradenhead 2

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE					
	Bradenhead			INTERM		
	BH	Int	Csg	Int	Csg	
TIME	<u>Ø</u>		<u>26</u>			
5 min	<u>Ø</u>		<u>26</u>			
10 min	<u>Ø</u>		<u>26</u>			
15 min	<u>Ø</u>		<u>26</u>			
20 min						
25 min						
30 min						

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	☒	
Nothing		
Gas	☒	
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ☐ FRESH ☐ SALTY ☐ SULFUR ☐ BLACK ☐

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD Ø INTERMEDIATE N/A

REMARKS:

bradenhead then down to nothing in approx
one minute

By John Dockter
HSE Tech
(Position)

Witness _____

E-mail address JDockter@EnduringResources.com

7/10/19