NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District III/3distric.htm

NMOCD
MAY 31 2019
DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5-30-19 Operator Hilcorp Energy Co API #30-0 39-07836

Property Name SJ 30-5 Ut Well No. 24 Location: Unit ___ Section 16 Township 30 Range 5

Well Status(Shut-In or Producing) Initial PSI: Tubing 102 Intermediate N/A Casing 104 Bradenhead 44

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE Bradenhead BH	Int	Csg	INTERM Int	Csg
TIME 5 min	0		104		
10 min	0		104		
15 min	0		104		
20 min	0		105		
25 min	0		105		
30 min	0		105		

FLOW CHARACTERISTICS	BRADENHEAD	INTERMEDIATE
Steady Flow	✓	
Surges		
Down to Nothing		
Nothing		
Gas	✓	
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR____ FRESH____ SALTY____ SULFUR____ BLACK____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 10 INTERMEDIATE N/A

REMARKS: BH Medium Blow - 0 at 5 minutes but blowing - 10 - Blew while 30 minute test

By AC Greg C

(Position)

Witness Monica Kuehling

Gas analysis all strings

E-mail address _____