



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

NMOC

JUL 01 2019

DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6-28-19 Operator H. Coy Energy API #30-0 39-30045
Property Name Arizona Carolina A Well No. 4A Location: Unit E Section 24 Township 25 Range 4
Well Status (Shut-In or Producing) Initial PSI: Tubing 86 Intermediate 0 Casing 87 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	0	87	0	89
10 min	0	0	88	0	89
15 min	0	0	88	0	89
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	/	/
Nothing		
Gas	/	/
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 0

REMARKS:

Long puff when opened - Nothing after
5 min shut-in - Int blow to dead at 4 seconds
Nothing when opened after 5 min shut-in
By [Signature] Witness [Signature]

(Position)

E-mail address _____