



**NEW MEXICO ENERGY, MINERALS  
AND NATURAL RESOURCES DEPARTMENT**

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC, NM 87410  
(505 334-6178 FAX: (505) 334-6170  
<http://www.emnrd.state.nm.us/ocd/>

**BRADENHEAD TEST REPORT**  
(Submit 2 copies to above address)

Date of Test 6-14-19 Operator BPX API # 3004526798

Property Name Davis 1 Location: Unit E Section 23 Township 32 Range 11  
(Well Name and Number)

Pressure (Shut-in or Producing) Producing Tubing 9 Intermediate N/A Casing 20 Bradenhead 18

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	$\emptyset$	20	N/A	N/A	N/A		N/A
10 minutes	$\emptyset$	20					
15 minutes	$\emptyset$	20				✓	
20 minutes							
25 minutes						✓	
30 minutes							
5 minute SI	$\emptyset$	20					

NMOCD

JUL 11 2019

DISTRICT III

If bradenhead flowed water, check all of the descriptions that apply below:

Clear \_\_\_\_\_ Fresh \_\_\_\_\_ Salty \_\_\_\_\_ Sulfur \_\_\_\_\_ Black \_\_\_\_\_

5 Minute Shut-in Bradenhead  $\emptyset$  Intermediate N/A

REMARKS: Slim hole design. Samples Taken: BH - 7008, T-1013, & C - Gas 198  
Whisper down to nothing in 40 sec at start of test. No flow after. Huff  
for 2 sec at end of test. Compressor on site.

By Eugenia Hami Hon  
Technician

Witness \_\_\_\_\_

(Position)