



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170

<http://emnr.state.nm.us/ocd/District/III/3district.htm>

NMOC

MAY 30 2019

DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5-29-19 Operator H. Corp Energy Co API #30-0 45-34776
Property Name Allison W. Well No. 610 Location: Unit 11 Section 16 Township 3 Range 6
Well Status (Shut-In or Producing) Initial PSI: Tubing 148 Intermediate 265 Casing 234 Bradenhead 231

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	0	64	232	0	236
10 min	0	63	231	0	236
15 min	0	62	234	0	236
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	✓	✓
Nothing		
Gas	✓	✓
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 6

REMARKS:

BH Med blow to clear at 1 min 30 seconds.
Nothing when opened after 5 min shut-in. Int fell while
BH open. Int. Med blow when opened to clear at 2 min
30 sec.

By Bradley Humphill

Witness Monica Kunkling

(Position)

E-mail address _____

Med. blow
when opened
after 5 min
shut-in