NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District III/3distric.htm

NMOCD
JUL 11 2019
DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7-10-19 Operator Enduring Res. API #30-0 39-06918

Property Name Rincon Unit Well No. 127 Location: Unit ___ Section 28 Township 27 Range 6

Well Status(Shut-In or Producing) Initial PSI: Tubing 74 Intermediate 211 Casing 79 Bradenhead 9

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

Testing	Bradenhead BH	Bradenhead Int	Bradenhead Csg	INTERM Int	INTERM Csg
TIME 5 min	0	211	80	22	68
10 min	0	211	81	0	63
15 min	0	211	81	0	60
20 min	0	211	82	0	57
25 min				0	55
30 min				0	53

FLOW CHARACTERISTICS

	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	✓	✓
Nothing		
Gas	✓	✓
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR_____ FRESH_____ SALTY_____ SULFUR_____ BLACK_____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 9 INTERMEDIATE 0

REMARKS: BH down to vapors in 1 seconds. 0 at 5 min w. th vapors. 10-15-20 to dead. Int had blow when opened - to vapors at 15 min - 20-25 dead beginning full 30 min test

By John Dockter Witness Monica Sinkling

HSE Tech (Position)

Gas analysis all strings
Well bore schematic

E-mail address JDockter@EnduringResources.com

Int blow after 5 min shut in