



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

MECHANICAL INTEGRITY TEST REPORT

(TA OR UIC)

Date of Test 7.11.19 Operator Tride Energy API # 30-0 43-20532

Property Name San Isidro Unit 15 Well # 4 Location: Unit D Sec 15 Twn 20 Rge 3

Land Type:

State _____
Federal _____
Private _____
Indian _____

NMOC
JUL 11 2019
DISTRICT III

Well Type:

Water Injection _____
Salt Water Disposal _____
Gas Injection _____
Producing Oil/Gas ☒
Pressure observation _____

Temporarily Abandoned Well (Y/N): _____ TA Expires: 7.11.2024

Casing Pres. 0
Bradenhead Pres. 0
Tubing Pres. 1st
Int. Casing Pres. PTA

Tbg. SI Pres. _____
Tbg. Inj. Pres. _____

Max. Inj. Pres. _____

Pressured annulus up to 610 psi. for 30 mins. Test passed failed

REMARKS:

Packer Set 3780

top perf 3840

Chart kept by operator

By John P. Pumper
(Operator Representative)
PEC Pumper
(Position)

Witness Monica Fuchling
(NMOC)

Revised 02-11-02