



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3distric.htm](http://emnr.state.nm.us/ocd/District%20III/3distric.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5/17/19 Operator Reddy Production API #30-0 39-21258

Property Name Chacon Jic. Ap. D Well No. 4 Location: Unit P Section 9 Township 23 Range 3

Well Status (Shut-In or Producing) Initial PSI: Tubing 52 Intermediate NA Casing 19 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE			FLOW CHARACTERISTICS	
	BH	Bradenhead Int	Csg	BRADENHEAD	INTERMEDIATE
5 min	0		19	Steady Flow	
10 min	0		19	Surges	
15 min	0		19	Down to Nothing	
20 min				Nothing	
25 min				Gas	
30 min				Gas & Water	
				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE NA

REMARKS:

Could hear small puff of gas when opened, then nothing. Nothing after 5 min shut in. Note this well has a packer in the casing, that's why casing pressure is low.

By Jay JF
Lense Manager
(Position)

Witness _____

E-mail address ttixier@crownguest.com

NMOCO
JUN 05 2019
DISTRICT III