



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emmr.state.nm.us/ocd/District III/3district.htm](http://emmr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5/17/19 Operator Roddy Production API #30-0 39-21270

Property Name Chacon Jic. Ap. D Well No. 5 Location: Unit C Section 16 Township 23 Range 3

Well Status (Shut-In or Producing) Initial PSI: Tubing 67 Intermediate NA Casing 146 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			FLOW CHARACTERISTICS	
	BH	Bradenhead Int	Csg	BRADENHEAD	INTERMEDIATE
TIME					
5 min	<u>0</u>		<u>146</u>	Steady Flow	
10 min	<u>0</u>		<u>146</u>	Surges	
15 min	<u>0</u>		<u>146</u>	Down to Nothing	<u>/</u>
20 min				Nothing	
25 min				Gas	<u>/</u>
30 min				Gas & Water	
				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE NA

REMARKS:

Puff of gas about 2 to 3 seconds then nothing. Nothing
after 5 min shut in.

By Jay J. F.
Lease Manager
(Position)

Witness _____

E-mail address ttixier@crowquest.com

NMOC

JUN 05 2019

DISTRICT III