



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emmr.state.nm.us/ocd/District III/3ddistrict.htm](http://emmr.state.nm.us/ocd/District%20III/3ddistrict.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5/17/19 Operator Reddy Production API #30-0 39-24143

Property Name Chaco Jic. Ap. D Well No. 11 Location: Unit C Section 14 Township 23 Range 3

Well Status (Shut-In or Producing) Initial PSI: Tubing 23 Intermediate 30 Casing 30 Bradenhead 30

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead	Csg	Int	Csg
TIME					
5 min	0		30	0	30
10 min	0		30	0	30
15 min	0		30	0	30
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS		BRADENHEAD	INTERMEDIATE
Steady Flow			
Surges			
Down to Nothing			
Nothing	1 Vacuum	1 Vacuum	
Gas			
Gas & Water			
Water			

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD INTERMEDIATE

REMARKS:

Out side valve is Bradenhead, Inside valve is Intermediate.
Bradenhead - 0psi after 5min shut in, small vacuum. Intermediate had 2 to 3 second
vacuum then nothing. After 5min shut in - 0.98psi vacuum

By [Signature]
Lease Manager
(Position)

Witness [Signature]

E-mail address ttixier@crowquest.com

NMOCD

JUN 05 2019

DISTRICT III