



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/district.htm](http://emnrd.state.nm.us/ocd/District%20III/district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5/15/19 Operator Roddy Production API #30-0 43-20366
Property Name Chaco Jct. Ap. 0 Well No. 101 Location: Unit L Section 26 Township 23 Range 3
Well Status (Shut-In or Producing) Initial PSI: Tubing 52 Intermediate NA Casing 54 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Bradenhead		INTERM	
		Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>54</u>		
10 min	<u>0</u>		<u>54</u>		
15 min	<u>0</u>		<u>54</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing <u>1</u>	
Nothing	
Gas <u>1</u>	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE NA

REMARKS: Puff of gas for about 2 to 3 seconds then down to
nothing. Nothing after 5 min. shut in then reopened.

By July 7th
Lease Manager
(Position)

Witness _____

E-mail address ttixier@crownguest.com

WMOC
JUN 05 2019
DISTRICT III