

**NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT**

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3distric.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7/16/2019 Operator Hilcorp Energy Company API # 3003920393
Property Name JICARILLA K Well No. 15 Location: Unit I Section 01 Township 025N Range 005W
Well Status Flowing Initial PSI: Tubing 61 Intermediate Casing 62 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE					FLOW CHARACTERISTICS	
	BRADENHEAD			INTERM		BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg		
5 min	0		62			Steady Flow	
10 min	0		62			Surges	
15 min	0		62			Down to Nothing	
20 min						Nothing	Y
25 min						Gas	
30 min						Gas & Water	
						Water	

If Bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ☐ FRESH ☐ SALTY ☐ SULFUR ☐ BLACK ☐

If Intermediate flowed water, check all of the descriptions that apply below:

CLEAR ☐ FRESH ☐ SALTY ☐ SULFUR ☐ BLACK ☐

5 MINUTE SHUT-IN PRESSURE Bradenhead 0 Intermediate

REMARKS:

Test submitted 7/8/2019 for this well was incorrect (data entered was for the Jicarilla K 15E). This is the correct information for this well. TSTM blew DTN in 2 secs through 1" valve.

Tested By Brandon Noble Witness