



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 18-JUL-2019 Operator HILCORO API #30-0 39-23465
Property Name LIMMITH B Well No. 26 Location: Unit A Section 9 Township 24 Range 3
Well Status(Shut-In or Producing) Initial PSI: Tubing 95 Intermediate 0 Casing 67 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	0	67	0	67
10 min	0	0	67	0	67
15 min	0	0	67	0	67
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	X
Nothing	X
Gas	X
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 0

REMARKS:

OPENED THE BRADENHEAD AND NOTHING CAME OUT.
OPENED THE INTERMEDIATE AND IT BLEW DOWN TO NOTHING
IN 10 SECONDS

By Jeremy Vigil
Jeremy Vigil - MSO
(Position)

Witness [Signature]

E-mail address _____

NMOCD

JUL 19 2019

DISTRICT III