NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District III/3district.htm

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 17-JULY-2019 Operator HILLCAP API #30-0 39 23871

Property Name HARRINGTON Well No. 4 Location: Unit ___ Section 31 Township 27 Range 7

Well Status(Shut-In or Producing) Initial PSI: Tubing 93 Intermediate NA Casing 98 Bradenhead 59

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

Testing	Bradenhead BH	Bradenhead Int	Bradenhead Csg	INTERM Int	INTERM Csg
TIME 5 min	7	NA	101		
10 min	6		102		
15 min	5		103	NA	
20 min	5		103		
25 min	5		104		
30 min	5		104		

FLOW CHARACTERISTICS

	BRADENHEAD	INTERMEDIATE
Steady Flow	X	
Surges		
Down to Nothing		
Nothing		NA
Gas		
Gas & Water		
Water	X	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR X FRESH ___ SALTY ___ SULFUR ___ BLACK ___

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 56 INTERMEDIATE NA

REMARKS: OPENED THE BRADENHEAD AND WATER FLOWED FOR THE ENTIRE TEST. BRADENHEAD WAS PLUMBED TO THE BGT. MADE 452 GALLONS. REQUESTED A WATER ANALYSIS AND WELLBORE SCHEMATIC

By Jeff Miller Witness [illegible]

(Position)

E-mail address

NMOCD
JUL 17 2019
DISTRICT III