



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 18-JULY-2018 Operator HILCORP API #30-0 39-25066
Property Name LINDAITHB Well No. 78 Location: Unit 4 Section 6 Township 24 Range 2
Well Status(Shut-In or Producing) Initial PSI: Tubing 17 Intermediate N/A Casing 68 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead		INTERM		
	BH	Int	Csg	Int	Csg
TIME	0	N/A	68		
5 min	0		68		
10 min	0		68		
15 min	0		68		
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing		
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS: OPENED THE ~~BRADENHEAD~~ BRADENHEAD AND NOTHING CAME OUT

By Jeremy Vigil
MSO
(Position)

Witness [Signature]

E-mail address _____

NMOCD
JUL 19 2019
DISTRICT III