



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6170 FAX: (505) 334-6170
<http://emrmd.state.nm.us/ocd/District%20aztec.htm>

inspection iMPK 197028512

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4-17-19 Operator BPK API #30-0 4523257
Property Name Bolack Well No. 2 Location: Unit 6 Section 19 Township 12N Range 8W
Well Status (Shut-In or Producing) Initial PSI: Tubing 79 Intermediate N/A Casing 123 Bradenhead 16

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM		
	BH	Int	Csg	Int	Csg	
TIME						
5 min	2.5		124.3			
10 min	1.8		124.7			
15 min	1.8		127.1			
20 min	1.2		127.4			
25 min	1.2		127.7			
30 min	1.0		124.2			
5 min shut-in	15.4		122.9			

FLOW CHARACTERISTICS
BRADENHEAD INTERMEDIATE

Steady Flow	
Surges	
Down to Nothing	
Nothing	
Gas	
Gas & Water	
Water	X

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ☒ FRESH ☐ SALTY ☐ SULFUR ☐ BLACK ☐

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 15.4

INTERMEDIATE N/A

REMARKS:

No blow down due to sampling. Samples T-7008, C-7075, & ~~9# 7009~~ ^{Cancelled}
Steady flow of water through out test. Took water sample off BH
and off water side of separator for production water sample.

By Eugenia Hamilton

Witness _____

Technician
(Position)

E-mail address Eugenia.H@pexinc.biz

JUL 11 2019

DISTRICT III