



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3distric.htm)

NMOC

JUL 24 2019

DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7.24.19 Operator BP America API #30-0 45-28601
Property Name Gallegos Canyon W 13 SW 4 Well No. 1 Location: Unit 5 Section 13 Township 29 Range 13
Well Status (Shut-In or Producing) Initial PSI: Tubing 240 Intermediate 1/A Casing 3 Bradenhead 4

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	Bradenhead				
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>3</u>		
10 min	<u>0</u>		<u>3</u>		
15 min	<u>0</u>		<u>3</u>		
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	<u>/</u>	
Nothing		
Gas	<u>/</u>	
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 1/A

REMARKS:

Med blow to dead in 4 seconds. Nothing
when opened after 5 min shut in.

By

Robert Lee

Witness

Monica Kuehling

(Position)

E-mail address