



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170

[http://omnrd.state.nm.us/ocd/District III3/district.htm](http://omnrd.state.nm.us/ocd/District%20III3/district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8-5-19 Operator Dominion Pro API #30-0 31-20745
Property Name SFRP Well No. 42 Location: Unit E Section 7 Township 17 Range 8
Well Status (Shut-In) or Producing) Initial PSI: Tubing 0 Intermediate 0 Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>0</u>		
10 min	<u>0</u>		<u>0</u>		
15 min	<u>0</u>		<u>0</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	☒
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR 0 FRESH 0 SALTY 0 SULFUR 0 BLACK 0

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 0

REMARKS:

nothing when opened Bth, nothing after
5 min shut in

By [Signature]
(Position)

Witness _____

E-mail address _____

NMOCD

AUG 19 2019

DISTRICT III