



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emrdr.state.nm.us/ocd/District III/3distric.htm](http://emrdr.state.nm.us/ocd/District%20III/3distric.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7-29-19 Operator: Enervest Operating, LLC API #30-0 39-22000

Property Name Jic. Cent. 148 Well No. 18 Location: Unit F Section 23 Township 25N Range 5W

Well Status (Shut-In or Producing) Initial PSI: Tubing 89 Intermediate Casing 94 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>94</u>		
10 min	<u>0</u>		<u>94</u>		
15 min	<u>0</u>		<u>94</u>		
20 min	<u>0</u>		<u>94</u>		
25 min	<u>0</u>		<u>94</u>		
30 min	<u>0</u>		<u>94</u>		

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing	<u>✓</u>	
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE

REMARKS:

By Orrin Sandoval Orrin Sandoval Witness

(Position)

E-mail address

NMOC
AUG 22 2019
DISTRICT III