



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test 7-22-19 Operator: EnerVest Operating, LLC API # 30-039-22522

Property Name: jic cont 146 Well No 39 Location: Unit j Section: 3 Township: 25n Range: 5w

Well Status (Shut-In or Producing) Initial PSI: Tubing 51 Intermediate 57 Casing 57 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>57</u>		
10 min	<u>0</u>		<u>57</u>		
15 min	<u>0</u>		<u>57</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing Puff <u>x</u>	
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE

REMARKS:

 nothing on braiding head pressure was too low to record

By orel browning

Witness

Lease Operator 3
(Position)

NMOC
JUL 31 2019
DISTRICT III