

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test 7-17-19 Operator: **Enervest Operating, LLC** API # 30-039-22897

Property Name: Jicarilla A Well No. 8E Location: Unit P Section: 17 Township: 26N Range 5W

Well Status (Shut-In or **Producing**) Initial PSI: Tubing 55 Intermediate Casing 55 Braden head 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0		55		
10 min	0		55		
15 min	0		55		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	X
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE

REMARKS:

No Blow

By Rodale Curley

Witness _____

Lease Operator
(Position)

E-mail address

NMOC

JUL 31 2019

DISTRICT 11