



NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
[http://omnrd.state.nm.us/ocd/District III3district.htm](http://omnrd.state.nm.us/ocd/District%20III3district.htm)

**BRADENHEAD TEST REPORT**

(submit 1 copy to above address)

Date of Test 7-24-19 Operator Benson Montin Greer API #30-0 39-23214  
Property Name EPCMU Well No. 35 Location: Unit M Section 9 Township 26N Range 1E  
Well Status (Shut-In or Producing) Initial PSI: Tubing 80 Intermediate N/A Casing 11 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>11</u>		
10 min	<u>0</u>		<u>11</u>		
15 min	<u>0</u>		<u>11</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	<u>✓</u>
Nothing	<u>✓</u>
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR        FRESH        SALTY        SULFUR        BLACK       

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE       

REMARKS:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

By Bennie Velozquez  
Lease operator  
(Position)

Witness       

E-mail address       

**NMOCD**  
**AUG 05 2019**  
**DISTRICT III**