



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7/15/19 Operator ENDURING RESOURCES IV LLC API #30-039-25404

Property Name RINCON UNIT NP Well No. 306 Location: Unit M Section 34 Township 27N Range 07W

Well Status (Shut-In or Producing) Initial PSI: Tubing 63 Intermediate N/A Casing 66 Bradenhead 3

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	Ø		68		
10 min	Ø		69		
15 min	Ø		70		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	
Gas	
Gas & Water	
Water	

NMOC

JUL 30 2019

DISTRICT III

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD Ø

INTERMEDIATE N/A

REMARKS:

bradenhead bled down to nothing in approx
twenty seconds

By John Dockter
HSE Tech
(Position)

Witness _____

E-mail address JDockter@EnduringResources.com

7/29/19