submitted in lieu of Form 3160-5

UNITED STATES

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

THE HER () THE ACT		
Sundry Notices and Reports on Wells 7006 APR 25 AM 10 10 RECEIVED 070 FARMINGTON NM	5.	Lease Number NMSF-078626
GAS 070 FARMING FOR THE	0.	If Indian, All. or Tribe Name
. Name of Operator	7.	Unit Agreement Name
BURLINGTON RESCURCES OIL & GAS COMPANY LP	8.	San Juan 32-9 Unit Well Name & Number
Address & Phone No. of Operator	- 0.	
PO Box 4289, Farmington, NM 87499 (505) 326-9700	9.	SJ 32-9 Unit #260S API Well No.
Location of Well Footogo See, T. P. M.	-	30-045-33362
Location of Well, Footage, Sec., T, R, M	10.	Field and Pool
VIII OURSEN 1050) PSI O 710) PFI See 10 T21N DOW NADM	Bas	in Fruitland Coal
Unit I (NESE), 1950' FSL & 710' FEL, Sec. 10, T31N, R9W, NMPM	11.	County and State San Juan Co., NM
Type of Submission Type of Action Notice of Intent Abandonment Change of Plans X Ott Recompletion New Construction Non-Routine Fracturing Casing Repair Water Shut off Final Abandonment Altering Casing Conversion to Injection	ner –casing	Report
Notice of Intent Abandonment Change of Plans X Ott Recompletion New Construction Non-Routine Fracturing Casing Repair Water Shut off Final Abandonment Altering Casing Conversion to Injection 3. Describe Proposed or Completed Operations /22/06 MIRU Aztec #580. NU BOP. PT – OK. PT casing to 600#/30 min. Good test. RIH w/8-3/4" bit	t & tagger	d @ 192'. D/O cement and ther
Notice of Intent Abandonment Recompletion New Construction Non-Routine Fracturing Casing Repair Water Shut off Final Abandonment Altering Casing Conversion to Injection 3. Describe Proposed or Completed Operations Altering Casing to 600#/30 min. Good test. RIH w/8-3/4" bit head to 3173'. Reached on 4/24/06. Circ hole. RIH w/73 jts of 7", 20#, J-55 casing and landed @ 3172 os x (57 cf - 10 bbl slurry) Scavenger Type III cement. Lead w/409 sx (871 cf - 155 bbl slurry) Premiur. CM-1, .4% FL-52, .4% SMS. Tailed w/90 sx (124 cf - 22 bbl slurry) Type III w/1% CaCl, .25#/sx Celleisplaced. Circ. 40 bbls to surface. Installed WH. RD & released rig @ 0600 hrs 4/25/06. The casing PT	t & tagged 2. RU BJ m Lite w/2 oflake, 29	d @ 192'. D/O cement and ther Pumped preflush ahead of 3% CaCl, .25#/sx Celloflake, 6 FL-52. Dropped plug and
Notice of Intent Abandonment	t & tagged 2. RU BJ m Lite w/2 oflake, 29	d @ 192'. D/O cement and then Pumped preflush ahead of 3% CaCl, .25#/sx Celloflake, 6 FL-52. Dropped plug and
Notice of Intent Recompletion New Construction New Construction Non-Routine Fracturing Casing Repair Water Shut off Final Abandonment Altering Casing Conversion to Injection 3. Describe Proposed or Completed Operations /22/06 MIRU Aztec #580. NU BOP. PT – OK. PT casing to 600#/30 min. Good test. RIH w/8-3/4" bit head to 3173'. Reached on 4/24/06. Circ hole. RIH w/73 jts of 7", 20#, J-55 casing and landed @ 3172 9 sx (57 cf – 10 bbl slurry) Scavenger Type III cement. Lead w/409 sx (871 cf – 155 bbl slurry) Premiur .CM-1, 4% FL-52, 4% SMS. Tailed w/90 sx (124 cf – 22 bbl slurry) Type III w/1% CaCl, .25#/sx Cells isplaced. Circ. 40 bbls to surface. Installed WH. RD & released rig @ 0600 hrs 4/25/06. The casing P is and results will be reported on next report.	t & tagged 2. RU BJ m Lite w/2 oflake, 29	d @ 192'. D/O cement and ther Pumped preflush ahead of 3% CaCl, .25#/sx Celloflake, 6 FL-52. Dropped plug and
Notice of Intent Abandonment Recompletion New Construction Non-Routine Fracturing Casing Repair Water Shut off Final Abandonment Altering Casing Conversion to Injection 3. Describe Proposed or Completed Operations Altering Casing to 600#/30 min. Good test. RIH w/8-3/4" bit head to 3173'. Reached on 4/24/06. Circ hole. RIH w/73 jts of 7", 20#, J-55 casing and landed @ 3172 9 sx (57 cf - 10 bbl slurry) Scavenger Type III cement. Lead w/409 sx (871 cf - 155 bbl slurry) Premiur CM-1, 4% FL-52, 4% SMS. Tailed w/90 sx (124 cf - 22 bbl slurry) Type III w/1% CaCl, 25#/sx Celleisplaced. Circ. 40 bbls to surface. Installed WH. RD & released rig @ 0600 hrs 4/25/06. The casing P is and results will be reported on next report.	t & tagged 2. RU BJ n Lite w/2 oflake, 2% I will be d	i @ 192'. D/O cement and then. Pumped preflush ahead of 3% CaCl, .25#/sx Celloflake, 6 FL-52. Dropped plug and conducted by the completion
Notice of Intent Abandonment Recompletion New Construction Non-Routine Fracturing Casing Repair Water Shut off Final Abandonment Altering Casing Conversion to Injection 3. Describe Proposed or Completed Operations Altering Casing to 600#/30 min. Good test. RIH w/8-3/4" bit head to 3173'. Reached on 4/24/06. Circ hole. RIH w/73 jts of 7", 20#, J-55 casing and landed @ 3172 9 sx (57 cf - 10 bbl slurry) Scavenger Type III cement. Lead w/409 sx (871 cf - 155 bbl slurry) Premiur CM-1, 4% FL-52, 4% SMS. Tailed w/90 sx (124 cf - 22 bbl slurry) Type III w/1% CaCl, .25#/sx Celle isplaced. Circ. 40 bbls to surface. Installed WH. RD & released rig @ 0600 hrs 4/25/06. The casing Pig and results will be reported on next report.	t & tagged 2. RU BJ n Lite w/2 oflake, 2% I will be d	i @ 192'. D/O cement and ther. Pumped preflush ahead of 3% CaCl, 25#/sx Celloflake, 6 FL-52. Dropped plug and conducted by the completion
Notice of Intent Abandonment Recompletion New Construction Non-Routine Fracturing Casing Repair Water Shut off Final Abandonment Altering Casing Conversion to Injection 3. Describe Proposed or Completed Operations Altering Casing to 600#/30 min. Good test. RIH w/8-3/4" bit head to 3173'. Reached on 4/24/06. Circ hole. RIH w/73 jts of 7", 20#, J-55 casing and landed @ 3172 9 sx (57 cf - 10 bbl slurry) Scavenger Type III cement. Lead w/409 sx (871 cf - 155 bbl slurry) Premiur CM-1, 4% FL-52, 4% SMS. Tailed w/90 sx (124 cf - 22 bbl slurry) Type III w/1% CaCl, .25#/sx Celleisplaced. Circ. 40 bbls to surface. Installed WH. RD & released rig @ 0600 hrs 4/25/06. The casing Pig and results will be reported on next report.	t & tagged 2. RU BJ n Lite w/2 oflake, 2% I will be d	i @ 192'. D/O cement and then. Pumped preflush ahead of 3% CaCl, .25#/sx Celloflake, 6 FL-52. Dropped plug and conducted by the completion