



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/district.htm](http://emnr.state.nm.us/ocd/District%20III/district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4-22-19 Operator Black Hawk API #30-0 39-25911

Property Name Jicarrilla Well No. 3 Location: Unit 0 Section 5 Township 30N Range 30E

Well Status (Shut-In or Producing) Initial PSI: Tubing _____ Intermediate ✓ Casing 18 Bradenhead 45

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	<u>1</u>	<u>✓</u>	<u>18</u>		
10 min	<u>0</u>	<u>✓</u>	<u>18</u>		
15 min	<u>0</u>	<u>✓</u>	<u>18</u>		
20 min	<u>0</u>	<u>✓</u>	<u>18</u>		
25 min	<u>0</u>	<u>✓</u>	<u>18</u>		
30 min	<u>0</u>	<u>✓</u>	<u>18</u>		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing <u>✓</u>	
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD _____ INTERMEDIATE _____

REMARKS: Had 45 lbs of pressure on BH Blew Down to nothing.

By Mett

Witness _____

(Position)

E-mail address _____

NMOCD

JUN 24 2019

DISTRICT III