



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170

[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

NMOC

2019 20 2019

DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8.20.19 Operator Elkay Energy Co. API #30-0 39-29415
Property Name SS 28766 Well No. 558 Location: Unit 12 Section 12 Township 28 Range 7
Well Status (Shut-In or Producing) Producing Initial PSI: Tubing 61 Intermediate 0 Casing 73 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM		
	Bradenhead					
	BH	Int	Csg	Int	Csg	
TIME						
5 min	0	0	74	0	75	
10 min	0	0	75	0	74	
15 min	0	0	75	0	73	
20 min						
25 min						
30 min						

FLOW CHARACTERISTICS		
BRADENHEAD	INTERMEDIATE	
Steady Flow		
Surges		
Down to Nothing	✓	
Nothing		✓
Gas	✓	
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 0

REMARKS:

Well shut to dead at 2 seconds - nothing when
opened after 5 min shut in - Int - nothing
when opened - Well started flowing 10 min - nothing
By Alm. Jr Witness Monica Furling when opened
after 5 min shut in.

(Position)

E-mail address _____