

Form 3160-5 (August 2007)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

JUL 2 5 2019

FORM APPROVED OMB No. 1004-0137 Expires: July 31, 2010

Farmington Field Office 5. Lease Serial No.

	ment NN	1SF080917							
SUN	NDRY NOTICES AND REPO	Min	ame						
Do not us	e this form for proposals t	to drill or	to re-ente	er an					
abandoned	well. Use Form 3160-3 (A	(PD) for s	such propo	osals.					
SI	JBMIT IN TRIPLICATE - Other inst	7. If Unit of CA/Agreement, Name and/or No.							
1. Type of Well									
Oil Well X Gas Well Other					8. Well Name and No.				
			ATLANTIC B COM 9A						
2. Name of Operator		9. API Well No.							
	Hilcorp Energy Compa				3004522977				
3a. Address		1	No. (include are		10. Field and Pool or Exploratory Area				
382 Road 3100, Aztec, N		505-599-34	400	11. Country or Parish, State	PC/BLANCO MV				
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description)			DOLONI		Name Manada a				
Surface Unit J (NWSE),	34, T031N	, R010W		SAN JUAN	, New Mexico				
12. CHECK	THE APPROPRIATE BOX(ES)	) TO INDIC	CATE NATU	RE OF NOT	ICE, REPORT OR OTHE	R DATA			
TYPE OF SUBMISSION			TY	PE OF AC	TION				
Notice of Intent	Acidize	Deeper	n	Пр	roduction (Start/Resume)	Water Shut-Off			
Troube of Intent	Alter Casing		e Treat		eclamation	Well Integrity			
X Subsequent Report	Casing Repair		onstruction		ecomplete	X Other			
A Subsequent Report	Change Plans		nd Abandon		emporarily Abandon	Final Reclamation			
Final Abandonment Notice	Convert to Injection	Plug B			Vater Disposal	Tillal Reclamation			
13. Describe Proposed or Completed Ope						1 1 6			
determined that the site is ready for for final reclamation was co	Abandonment Notices must be filed onl final inspection.)  Completed on 6/28/2019 for sector Bob Switzer and rec	the subj	ect P&A'd	location.	A reclamation inspec nation BMPs on the su	tion was conducted on			
					AU6	0 7 2019			
					DIZIKI	CT III			
14. I hereby certify that the foregoing is to	rue and correct. Name (Printed/Typed)	)		-					
Kandis Roland			Title Op	erations/Re	egulatory Technician - S	r.			
/		эр		S. J.					
Signature Landio	toland		Date 7	7/24/2019					
	THIS SPACE FO	R FEDE	RAL OR S	TATE OFF	ICE USE				
Approved by				_					

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

entitle the applicant to conduct operations thereon.

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would

Office

RCC Reclamation Completion		Location Name: Atlantic B Com 9A				Date: Revision 3 (3/21/17)							
			UL-Sec-Twn-Rng: J 34 031N 010W			Lat/Long: 36.85197, -107.86685 NAD 27							
Surface Owner:				Lease# SF-080917	Lease# SF-080917				County/State: SAN JUAN, NM				
Pipeline Owner: ENT // ,				Jwin/CorLocate Well Name & Operator:									
Onsite: Chad Perkins			Contractor Heily Osifficial Services				Seed Mix:						
Interim Reclamation	Completed '			Final Reclamation		Incomplete N/A		Remediation	Completed	Incomplete	N/A		
Have pit sample results been approved		工	י דַ	3rd party pipeline removed	1	$\perp$		Facilities stripped					
Has water been removed from pit	TL	L	] !	Anchors removed	2	$\Box$	] [	Certificate of waste issued & approved					
Have pit marker photos been taken		T	71	Equipment and piping removed	1	$\mathbf{T}$		Depth:					
Has certificate of waste been issued & approved		匸	7 !	Power poles removed		2	7	Width:					
Have all pit contents been removed		$\top$	7	Cathodic protection removed	1	op	٦ [	Length:					
Has sample after content removal been taken	1	$\top$	٦ ١	Vegetative cages removed	М	V	7	Date of Excavation Start:		$\Box$			
Is location contoured	1	$\top$	۱ ۲	CMP's removed	$\sqcap$	V	7	Date of Excavation End:	П	$\Box$			
Is there 4' of cover over pit	1	$\top$	٦!	Non native gravel buried or removed	2	<u>_</u>	7	Date of Backfill Start:	$\Box$	$\Box$			
Has top soil been spread evenly	$\top$	$\top$	٦!	Noxious weeds removed or sprayed	门	12	$\succ$	Date of Backfill End:	$\Box$	$\Box$			
Has all non-native gravel been buried or removed	$\top$	十	۱ ۲	Insvasive weeds removed or sprayed	口	4	7	Yards Hauled Out:	$\Box$	$\Box$			
Has pit liner been removed	++	$\top$	٦ ١	Contouring complete			1	Impacted Soil Hauled To:	$\sqcap$	$\Box$			
Has all trash been removed	++	$\top$	۱ ۲	Top soil spread	1	$\top$	1	Yards Hauled In:	$\Box$	$\Box$			
Have all weeds been removed	++	$\top$	۱ ۲	Diversions clean and functional		$\neg$	1	Fresh Soil Hauled in From:		$\sqcap$			
Teardrop allows vehicle access to all facilities	++	$\top$	٦,	Silt trap clean and functional	2	o	1	Approval to backfill	$\Box$	aggregation			
Drainage ditches allow adequate run off	++	+	۱ ۲	Cattle guard / gates removed	-	1	*	Back fill mechanically compacted	$ egthinspace{-1pt}$	ightharpoonup	-		
All non-traffic areas disked property	++	$\top$	٦,	Cellar / mouse hole covered	$\vdash$	1/2	1	Facilities reset	_	$\vdash$	_		
All non-traffic areas seeded	1	+	۱ ا	Erosion under control	12	十	1	Trash and debri removed	$\sqcap$	ightharpoonup			
Seeded areas have been mulched	++	+	11	Location properly ripped	1	十	1	Close Out Completed	$\sqcap$	ightharpoonup			
Noxious weeds have been removed or sprayed	++	+-	۱ ۲	Location properly disked	2	十	1	Soil Removal Sundry Ready to be Filed		$\overline{}$	-		
Invasive weeds have been removed or sprayed	+	+	۱ ۲	Location seeded	<b>-</b>	<u> </u>	1		$\sqcap$	ightharpoonup	$\neg$		
Barriers set to deter traffic	++	+	۱ ۲	Photo transect installed	1	12	$\!$			$\rightarrow$			
Silt traps are functional	+	+	۱ ۲	Access road properly closed	$\vdash$	1/2	$\Box$			$\rightarrow$			
Culverts are functional	++	+	۱ ۲	Public use controlled	$\vdash$	1	1		$\overline{}$		_		
	++	+	۱ ۲	Barriers in place	₩	1	$\mathcal{H}$		$\vdash$	$\rightarrow$	_		
Upper diversion is functional  Erosion under control	+	+	$+$ $^{\dagger}$	Grazing controlled	₩	-	$\mathbb{H}$	· · · · · · · · · · · · · · · · · · ·		$\rightarrow$	_		
Photo transect installed	+++	+	۱ ۲	P&A marker installed & legible	<del>لر. ا</del>	-	ΉI		$\vdash$	<del></del>	-		
	++	+	۱ إ	Well sign removed	<del>"</del>	十	41			$\rightarrow$	_		
Have wellhead cages and jersey barriers been removed	++	+	<u>ا</u> ا	Growth at least 70%		<del>,  -</del>	┨		-+	$\rightarrow$	-		
Have reclamation pictures been taken Growth at least 70%	++	+	<u>ا</u> إ	Trash and debris removed from location	عجرا	4	41	· · · · · · · · · · · · · · · · · · ·	$\dashv$	$\rightarrow$			
	┿╌┼	+-	-	Final reclamation photos taken	-	一	┧	<b>-</b>		$\rightarrow$	_		
Agency Inspection Date:	+	+	<u>ا</u> إ	Agency inspection Date: 87/16/19	<del>الريا</del>	<del>-</del> 4-	1		$\dashv$	$\rightarrow$			
Sundry is ready to file	++	+	<b>-</b>	FAN Ready to be filed		+	$\dashv$		┌─┤	$\rightarrow$			
Comments:			-  I	Comments:			41	Comments:	—	$\boldsymbol{\sqcup}$			
·													