



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

MECHANICAL INTEGRITY TEST REPORT

(TA OR UTC)

Date of Test 8.19.19 Operator Dugan Production API # 30-0 45-24265

Property Name Stella Needs a Com Well # 1E Location: Unit Sec 36 Twn 30 Rge 14

Land Type:

State
Federal
Private
Indian

NMOCD
AUG 19 2019
DISTRICT III

Well Type:

Water Injection
Salt Water Disposal ✓
Gas Injection
Producing Oil/Gas
Pressure observation

Temporarily Abandoned Well (Y/N): TA Expires:

Casing Pres. 0 Tbg. SI Pres. Max. Inj. Pres. 1562
Bradenhead Pres. 0 Tbg. Inj. Pres.
Tubing Pres. 760
Int. Casing Pres.

Pressured annulus up to 360 psi. for 33 mins. Test passed failed

REMARKS:


dropped to 340 and held last 10 minutes of 33
minute test.

Supply 3635
packer 3546

By [Signature] (Operator Representative) Witness [Signature] (NMOCD)

(Position)

Revised 02-11-02



DUGAN

30 MIN.

30-045 24265

STELLA NEEDS A com #1E

NMOCB

AUG 19 2019

DISTRICT III

CHART POOL USA INC.
PORTAGE, INDIANA

Stella Needs A com #1E

METER _____

CHART PUT ON _____

TAKEN OFF _____

LOCATION _____

REMARKS _____

Witnessed by OCB

CHART NO. MP-1000-41R

(TO FIT)

Monahan
District
Passed
8.19.19

James

35

30

25

40
50