



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

MECHANICAL INTEGRITY TEST REPORT

(TA OR UIC)

Date of Test 8.29.19 Operator Hilcorp Energy API # 30-0 45.33583

Property Name Rio Bravo Well # 5 Location: Unit E Sec 27 Twn 31 Rge 13

Land Type:

State _____
Federal _____
Private _____
Indian _____

Well Type:

NMOCD
AUG 30 2019
DISTRICT III

Water Injection _____
Salt Water Disposal ☒
Gas Injection _____
Producing Oil/Gas _____
Pressure observation _____

Temporarily Abandoned Well (Y/N): (N) TA Expires: _____

Casing Pres. 20
Bradenhead Pres. 20
Tubing Pres. 1281
Int. Casing Pres. N/A

Tbg. SI Pres. _____
Tbg. Inj. Pres. _____

Max. Inj. Pres. 1300

Pressured annulus up to 560 psi. for 30 mins. Test passed/failed

REMARKS:

Had to zero pressure to test
Packer set 3445

top of plug 3487

Kill Check performed - good.

well integrity during test

By Aster Whisenand
(Operator Representative)

Witness Monica Fuchling
(NMOCD)

SWD Operator
(Position)

Revised 02-11-02